

centimeters


**HUD 765846**  
**HRB 204w**  
**DEFECTIVE SKIRT/FLOORING**



**22 8:33 AM**  
**JUNE 2024**

centimeters


HUD 765846  
HRB 204w  
DEFECTIVE SKIRT/FLOORING




22 8:33 AM  
JUNE 2024



**HUD 765846**  
**HRB 204w CONSTRUCTION DEFECTIVE**  
**SKIRT TO FLOOR GAP & HOLE**

 <p>ELMS.PCM@USA.COM YOUR DREAM OUR EXPERTISE PICTURE PERFECT CARE</p>	<p>ENVIRONMENTAL LAND MANAGEMENT SERVICES</p> <p><b>ELMS</b></p> <p>PROPERTY CARE MAINTENANCE DOING IT RIGHT THE FIRST TIME PHOTOGRAPHY INSPECTION</p>
---	--

**22 8:26 AM**  
**JUNE 2024**



**HUD 765846**

**HRB 204w CONSTRUCTION DEFECTIVE FLOORING**

**REFRIGERATOR FLOOR NOT LEVEL**

<small>ELMS.PCM@USA.COM</small>  <small>YOUR DREAM OUR EXPERTISE PICTURE PERFECT CARE</small>	<small>ENVIRONMENTAL LAND MANAGEMENT SERVICES</small> <b>ELMS</b> <small>PROPERTY CARE MAINTENANCE DOING IT RIGHT THE FIRST TIME PHOTOGRAPHY INSPECTION</small>
--	---

**22 11:48 AM**  
**JUNE 2024**

**HUD 765846**  
**HRB 204w CONSTRUCTION DEFECTS**  
**REFRIGERATOR CORNER WALL**




ELMS.PCM@USA.COM ENVIRONMENTAL LAND MANAGEMENT SERVICES  
**ELMS**  
PROPERTY CARE MAINTENANCE  
DOING IT RIGHT THE FIRST TIME  
PHOTOGRAPHY INSPECTION  
YOUR DREAM OUR EXPERTISE  
PICTURE PERFECT CARE

**22 8:29 AM**  
**JUNE 2024**

**HUD 765846**


**HRB204w CONSTRUCTION DEFECTIVE SKIRT  
<= REFRIGERATION CORNER WALL**

**centimeters**




The logo for ELMS Environmental Land Management Services is located in the bottom right corner. It features a small illustration of a house with a chimney and a lawn. To the right of the illustration, the text reads: "ENVIRONMENTAL LAND MANAGEMENT SERVICES" in blue, "ELMS" in large black letters, "PROPERTY CARE MAINTENANCE" in red, "DOING IT RIGHT THE FIRST TIME" in blue, and "PHOTOGRAPHY INSPECTION" in red. Below the illustration, it says "YOUR DREAM OUR EXPERTISE" and "PICTURE PERFECT CARE".

**22 8:32 AM  
JUNE 2024**



**HUD 765846**

**HRB 204w CONSTRUCTION DEFECTIVE FLOORING  
REFRIGERATOR BACK WALL NOT LEVEL**



**22 11:48 AM  
JUNE 2024**

**HUD 765846**

**HRB 204w CONSTRUCTION DEFECT**

**REFRIGERATOR CORNER BATHROOM POCKET DOOR WALL**

**NOTE: 204w SINK WALL/POCKET DOOR AND BATHROOM  
SHARED WALL FLOORING/SKIRT DEFECTIVE  
UNSEALED/ALLOWING WATER SEEPAGE OVER YEARS  
HRB NEGLECT/FAILURE TO REPAIR**



**22 12:53 PM  
JUNE 2004**